


Total Land Subsidence in the Hawk Rock Area, Maricopa and Pinal Counties
Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
Time Period of Analysis: 6.9 Years 05/15/2010 To 03/15/2017

© MDA 2010 - 2017


Explanation

05/15/2010 To 03/15/2017

Total Land Subsidence



- Subsidence Feature
- Hardrock
- Earth Fissures
- CAP Canal
- Highways and Interstates**
 - Interstate
 - US
 - State
 - Roads
 - Railway



1:200,000

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey.
 For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 6/20/2017

